





Machine manufacturer	Caterpillar				
Machine type	Scoop tram R1700G				
Engine manufacturer	Caterpillar				
Engine type	C11				
Engine certification	EPA TIER 3				
Engine power	263 kW				
Engine speed	1800 RPM				
Engine displacement	11,1 Litres				
Number of cylinders	6, in line				
Aspiration	Turbo charged and aftercooler				
Exhaust gas volume	3.143 m3/hour / 1500 kg/h				
Exhaust gas temperature	460-470°C				
Fuel	Diesel fuel, max.15 ppm Sulphur				


Filter type:	Johnson Matthey Mining-CRT 2 x 2012SL					
Regeneration:	Catalytic, continuously during operation					
Requirements:	ULSD Fuel, S< 50ppm Exhaust gas temperature >250°C for >50% of the operational time > 99% by particulate number					
Particulate reduction:						
NO2, CO and HC reduction:	Reduction					
Filter body:	Stainless Steel					











	ECOM T	est using H	leated Pr	obe Line -	No tempe	erature sen	sors
		Dua		tall Test #1 @ 1:56 PM) 1700 rpm		
	Contaminant	Intake	Conc %	Exhaust	Conc %	Reduction	Comments
Temp (⁰ C)	Ambiant Air	15.0		16.1			
emp (⁰ C)	Gas	n/a		n/a			
emp (⁰ C)	Sensor	22.8		22.2			
02	Oxygen	12.0%	12.00	12.0%	12	n/a	
00	Carbon Monoxide	283		10		96%	
002	Carbon Dioxide	6.7%	6.70	6.7%	6.60		
NO	Notrogen Oxide	292		293		0%	
NO2	Nitrogen Dioxide	22		17		23%	
NOx	Nitrous Oxide	314		310		1%	
DPM	Diesel Particulate Mater	9	18.70	1 19%	18.60	n/a	
	Total % Volume or Gases	19%					

VALE

Phase 2 – Results to Date RESULTS & COMMENTS No operator involvement for DPF regeneration; normal operations >Over-all the system operated very well with little maintenance & down time

>Operators need to minimize idle time to less than 20 minutes/hour due to < 250°C temperature which do not regenerate and cause accelerated plugging of filters

>DPF system malfunctioned at 630 hrs due to:

- DPF quality control issue which was identified and corrected by Johnson-Matthey, Germany
- Heat cured the rubber shock mounts resulting in excess vibration damage to DOC which moved inside of casing and blocked the filter (identified and heat shielding installed)

